

Blast monitoring summary



Beenleigh Quarry | July 2026 - September 2026

Blast Date	Blast No.	Vibration Type	Leaver Crt	Top of Vennor Dr	92 Peachey Rd	Quarry Office
08-Jul-26	2609	Ground Vibration (mm/s)	0.44	Did Not Register	0.39	0.69
08-Jul-26	2609	Airover Pressure (dBL)	107.10	Did Not Register	106.60	111.60
27-Jul-26	2610	Ground Vibration (mm/s)	0.78	Did Not Register	0.86	1.05
27-Jul-26	2610	Airover Pressure (dBL)	109.40	Did Not Register	105.80	110.10
13-Aug-26	2611	Ground Vibration (mm/s)	0.87	0.22	0.88	1.24
13-Aug-26	2611	Airover Pressure (dBL)	107.10	110.90	107.10	109.70
26-Aug-26	2612	Ground Vibration (mm/s)	0.33	0.08	0.34	0.61
26-Aug-26	2612	Airover Pressure (dBL)	110.40	112.40	109.20	113.60
09-Sep-26	2613	Ground Vibration (mm/s)	1.05	0.47	0.97	2.17
09-Sep-26	2613	Airover Pressure (dBL)	82.80	107.40	101.20	109.60

Results

All blast monitoring results from July 2026 - September 2026 are compliant with the site's Environmental Authority blasting limits. Monitoring locations are selected by the consultant based on blast profile and location on site. The result "Did Not Register" indicates no impact occurred at a level sufficient for the monitor to record.

Further information

Contact **Beau Patton**, Beenleigh Quarry Manager, on 0448 243 591 to provide feedback or request further information.