

## **Blast monitoring summary**

Beenleigh Quarry | July 2025 - September 2025

Blast Date	Blast No.	Vibration Type	Leaver Crt	Top of Vennor Dr	92 Peachey Rd	Quarry Office
08-Jul-25	958	Ground Vibration (mm/s)	0.78	0.11	0.50	1.23
08-Jul-25	958	Airover Pressure (dBL)	101.00	112.00	102.80	102.80
30-Jul-25	959	Ground Vibration (mm/s)	Did Not Register	Did Not Register	Did Not Register	Did Not Register
30-Jul-25	959	Airover Pressure (dBL)	Did Not Register	Did Not Register	Did Not Register	Did Not Register
			•	,		
25-Aug-25	961	Ground Vibration (mm/s)	0.29	Did Not Register	0.31	0.44
25-Aug-25	961	Airover Pressure (dBL)	104.20	Did Not Register	98.70	104.20
·			•			
09-Sep-25	960	Ground Vibration (mm/s)	0.46	Did Not Register	Did Not Register	0.87
09-Sep-25	960	Airover Pressure (dBL)	102.80	Did Not Register	Did Not Register	103.50

## Results

All blast monitoring results from July 2025 - September 2025 are compliant with the site's Environmental Authority blasting limits. Monitoring locations are selected by the consultant based on blast profile and location on site. The result "Did Not Register" indicates no impact occurred at a level sufficient for the monitor to record.

## **Further information**

Contact Beau Patton, Beenleigh Quarry Manager, on 0448 243 591 to provide feedback or request further information.

© 2020 Holcim (Australia) Pty Limited