

Holcim Australia & New Zealand Summarized Event Report Listing for 01 Jan 2021 to 31 Mar 2021

Event Date Reference Status Event Type Responsible Manager(s) Workgroup Description



Holcim Australia & New Zealand Summarized Event Report Listing for 01 Apr 2021 to 30 Jun 2021

Event Date Reference Status Event Type Responsible Manager(s) Workgroup Description



Holcim Australia & New Zealand Summarized Event Report Listing for 01 Jul 2021 to 30 Sep 2021

Community Complaint

Event Date	Reference	Status	Event Type	Responsible Manager(s)	Workgroup	Description			
Visual Amenity									
03-Jul-2021	333308	Closed	Community Complaint		Lynwood Quarry NSW	Community complaint received regarding light impacts in the evening			
05-Jul-2021	333309	Closed	Community Complaint		Lynwood Quarry NSW	Community complaint received regarding light impacts in the evening, ongoing for 2 weeks			



Complaint Register for Lynwood Quarry									
Incident Date	Incident Number	Primary Incider	Site Location	Detailed Description	Segment Responsible				
29/10/2021	INC-0192902	Environment	5344 Lynwood NSW Quarry	Dust complaint made to EPA from local resident following strong wind event	AGG-Aggregates				
01/12/2021	INC-0196058	Environment	5344 Lynwood NSW Quarry	At 3:40pm this afternoon Ben Hansel brought to my attention that we had a significant Diesel spill at the HME GO Line. On initial inspection Ben informed me he was Re fueling LO07 with Diesel and went to discuss with Kenny the Grader operator if he required any Diesel, Grease whilst he was going. It was at this point Ben realized that the fuel nozzle did not automatically cut off as the auto fill is faulty. This allowed Diesel to overflow	AGG-Aggregates				
				out the relief valve of the auto fill and the manual fill points.					