



Lynwood Quarry  
Complaints received in Q4 of 2025

Incident Date	Incident Number	Primary Incident	Site Location	Detailed Description
26/11/25	INC-0271709		Lynwood Quarry 5344	<p>At approx 3:15 on 26th November at Lynwood Quarry, high winds (=65kph) caused dust to generate from the southern excess sand emplacement and head east towards Maru. All work was stopped, two watercarts were deployed to the emplacement and applied water to suppress the dust. The QM coordinated the watercarts to ensure maximum effectiveness. 45 mins of concentrated efforts suppressed the stockpile to the point that one watercart was able to m</p> <p>Crusting agent was re applied during the night shift to ensure dust minimisation.</p>

ilan tip.

aintain suppression through the afternoon and night shift.



Lynwood Quarry  
Complaints received in Q3 of 2025

Incident Date	Incident Number	Primary Incident	Site Location	Detailed Description
---------------	-----------------	------------------	---------------	----------------------

No complaints received in Q3



Incident Date	Incident Number	Primary Incident	Site Location
---------------	-----------------	------------------	---------------

No Complaints recieved Q2 2025

**Lynwood Quarry**  
**Complaints received in Q2 of 2025**

**Detailed Description**



Lynwood Quarry  
Complaints received in Q1 of 2025

Incident Date	Incident Number	Primary Incident	Site Location	Detailed Description
---------------	-----------------	------------------	---------------	----------------------

No complaints received