

**Complaint Register for Lynwood Quarry** 

Incident Date	Incident Number	<b>Primary Incider</b>	Site Location	Detailed Description	<b>Segment Responsible</b>
29/10/2021	INC-0192902	Environment	5344 Lynwood NSW Quarry	Dust complaint made to EPA from local resident following strong wind event	AGG-Aggregates
01/12/2021	INC-0196058	Environment	5344 Lynwood NSW Quarry	At 3:40pm this afternoon Ben Hansel brought to my attention that we had a significant Diesel spill at the HME GO Line. On initial inspection Ben informed me he was Re fueling LO07 with Diesel and went to discuss with Kenny the Grader operator if he required any Diesel, Grease whilst he was going. It was at this point Ben realized that the fuel nozzle did not automatically cut off as the auto fill is faulty. This allowed Diesel to overflow out the relief valve of the auto fill and the manual fill points.	AGG-Aggregates