# Noise Monitoring Assessment

Lynwood Quarry, Marulan, NSW Quarter 1 Ending March 2021.



### Document Information

**Noise Monitoring Assessment** 

Lynwood Quarry, Marulan, NSW

Quarter 1 Ending March 2021

Prepared for: Holcim (Australia) Pty Ltd

Prepared by: Muller Acoustic Consulting Pty Ltd

PO Box 262, Newcastle NSW 2300

ABN: 36 602 225 132 P: +61 2 4920 1833

www.mulleracoustic.com

Document ID	Status	Date	Prepared By	Signed	Reviewed By	Signed
MAC180611-02RP11	Final	12 March 2021	Kristian Allen	Kler	Rod Linnett	PM LSH-

#### DISCLAIMER

All documents produced by Muller Acoustic Consulting Pty Ltd (MAC) are prepared for a particular client's requirements and are based on a specific scope, circumstances and limitations derived between MAC and the client. Information and/or report(s) prepared by MAC may not be suitable for uses other than the original intended objective. No parties other than the client should use or reproduce any information and/or report(s) without obtaining permission from MAC. Any information and/or documents prepared by MAC is not to be reproduced, presented or reviewed except in full.



#### CONTENTS

1	11	NTRODUCTION	5
2	Ν	IOISE CRITERIA	7
3	Ν	METHODOLOGY	9
	3.1	LOCALITY	9
	3.2	ASSESSMENT METHODOLOGY	9
4	R	ESULTS	. 13
	4.1	ASSESSMENT RESULTS - LOCATION N1	. 13
	4.2	ASSESSMENT RESULTS - LOCATION N2	. 14
	4.3	ASSESSMENT RESULTS - LOCATION N3	. 15
	4.4	ASSESSMENT RESULTS - LOCATION N4	. 16
5	С	DISCUSSION	. 17
	5.1	DISCUSSION OF RESULTS - LOCATION N1	. 17
	5.2	DISCUSSION OF RESULTS - LOCATION N2	. 17
	5.3	DISCUSSION OF RESULTS - LOCATION N3	. 17
	5.4	DISCUSSION OF RESULTS - LOCATION N4	. 17
6	C	ONCLUSION	. 19

APPENDIX A - GLOSSARY OF TERMS





#### 1 Introduction

Muller Acoustic Consulting Pty Ltd (MAC) has been commissioned by Holcim (Australia) Pty Ltd (Holcim) to complete a Noise Monitoring Assessment (NMA) for Lynwood Quarry (the 'quarry'), Marulan, NSW.

The monitoring has been conducted in accordance with the Lynwood Noise Management Plan (NMP) and in general accordance with the Noise Policy for Industry (NPI), at four representative monitoring locations. This assessment has been undertaken for the quarterly period ending March 2021, and forms part of the annual noise monitoring program to address conditions outlined in the Development Consent.

The assessment has been conducted in accordance with the following documents:

- NSW Environment Protection Authority (EPA), Noise Policy for Industry (NPI), 2017;
- Lynwood Quarry Noise Management Plan (NMP), 2016;
- Lynwood Quarry Environmental Protection Licence (EPL), 2013 (12939);
- Lynwood Quarry, Development Consent, 2005 (DA128-5-2005); and
- Australian Standard AS 1055:2018 Acoustics Description and measurement of environmental noise.

A glossary of terms, definitions and abbreviations used in this report is provided in Appendix A.





#### 2 Noise Criteria

The Lynwood Quarry Noise Management Plan (NMP), outlines the applicable noise criteria for residential receivers L1 – L16 surrounding the quarry, and are presented in **Table 1**.

Table 1 Noise Criteria <sup>1</sup>								
Location	Day (7am to 6pm)	Evening (6pm to 10pm)	Night (10	Night (10pm to 7am)				
Location	dB LAeq(15min)	dB LAeq(15min)	dB LAeq(15min)	dB LA1(1min)				
L1	35	35	35	45				
L2	35	35	35	45				
L3	35	35	35	45				
L4	35	37	35	46				
L5	35	35	35	46				
L6	35	37	36	46				
L7	38	38	35	55				
L8	39	38	36	55				
L9	39	39	37	56				
L10	42	42	40	53				
L11	35	35	35 <sup>1</sup>	47				
L12	37	37	36	47				
L13	40	38	37	47				
L14	35	35	35	47				
L15	35	35	35	47				
L16	35	35	35	45				

Note 1: Noise criteria adopted from the EPL.





#### 3 Methodology

#### 3.1 Locality

The quarry is located near Marulan, NSW approximately 4km west of the town centre. Receivers in the locality surrounding the quarry are primarily rural and residential. The quarry is surrounded by rural properties to the west, with the Hume Highway situated to the east and south of the site. Highway traffic is a dominant noise source in the area along with rural noise. The monitoring locations with respect to the quarry and assessed receivers are presented in the locality plan in **Figure 1** and presented in **Table 2**.

Table 2 Monitoring Location Addresses									
				Criteria	a dB				
NMP ID	EPL ID	Address	Day	Evening	Night	Night			
			LAeq(15min)	LAeq(15min)	LAeq(15min)	LA1(1min)			
N1	L1	1114 Carrick Road, Marulan	35	35	35	45			
N2	L6	End of Maclura Drive, Marulan	35	37	36	46			
N3	Northern Boundary,		35	35	35 <sup>2</sup>	47			
	LII	16038 Hume Highway, Marulan <sup>1</sup>	33	33	33	47			
N4	L12	Corner of Dorsett and Suffolk	37	37	36	47			
11/4	LIZ	Road, Marulan	31	31	30	41			

Note: Day - the period from 7am to 6pm Monday to Saturday or 8am to 6pm on Sundays and public holidays; Evening - the period from 6pm to 10pm; Night - the remaining periods.

#### 3.2 Assessment Methodology

The attended noise measurements were conducted in general accordance with the procedures described in Australian Standard AS 1055:2018, "Acoustics - Description and Measurement of Environmental Noise" and the Lynwood Quarry EPL. The measurements were carried out using a Svantek Type 1, 971 noise analyser on Tuesday 9 February 2021 and Thursday 11 February 2021. The acoustic instrumentation used carries current NATA calibration and complies with AS IEC 61672.1-2019-Electroacoustics - Sound level meters - Specifications. Calibration of all instrumentation was checked prior to and following measurements. Drift in calibration did not exceed ±0.5dBA.

Noise measurements were of 15-minutes in duration and where possible, throughout each survey the operator quantified the contribution of each significant noise source. Measurements were conducted at four locations (N1-N4) on Tuesday 9 February 2021 and Thursday 11 February 2021 to satisfy the requirements of the NMP.




Note 1: Intermediate noise monitoring point.

Note 2: Noise criteria adopted from the EPL.

Extraneous noise sources were excluded from the analysis to determine the LAeq(15min) quarry noise contribution for comparison against the relevant criteria. In the event of quarry attributed noise being above criteria, prevailing meteorological conditions for the monitoring period are sourced from the onsite meteorological station and analysed in accordance with Fact Sheet D of the NPI to determine the stability category present at the time of each attended measurement.

Where the quarry is inaudible, the contribution is estimated to be at least 10dBA below the ambient noise level.







#### 4 Results

#### 4.1 Assessment Results - Location N1

The monitored noise level contributions and observed meteorological conditions for each assessment period at Location N1 for the NMA are presented in **Table 3**.

Table 3 Operator-Attended Noise Survey Results – Location N1							
Date	Time o (lawa)	Descriptor (dBA re 20 µPa)			Matagralagy	Description and CDL dDA	
Date	Time (hrs)	LAmax	LAeq	LA90	Meteorology	Description and SPL, dBA	
						Wind 29-43	
					WD, CE	Birds 26-48	
00/00/2021	14:46	66	38	32	WD: SE	Operator 55-66	
09/02/2021	(Day)	66		32	WS: 1.5m/s	Quarry – Haul Trucks 26-33	
					Rain: Nil	(Multiple movements	
						7-10 minute duration)	
	Lynwoo	d Quarry L	Aeq(15min)	Contribution	1	<33	
					M/D. M	Insects 28-36	
11/00/0001	23:59	FF	20		WD: N	Distant Traffic <25-28	
11/02/2021	(Night)	55	39	29	WS: <0.5m/s	Train 30-55	
					Rain: Nil	Quarry Not Audible	
	Lynwoo	<30					
	Lynwo	<40					



#### 4.2 Assessment Results - Location N2

The monitored noise level contributions and observed meteorological conditions for each assessment period at Location N2 for the NMA are presented in **Table 4**.

Table 4 Operator-Attended Noise Survey Results – Location N2							
Б. 1	Time (hrs)	Descript	or (dBA re	20 μPa)	Meteorology	Description and CDL dDA	
Date	Time (fils)	LAmax	LAeq	LA90	Meteorology	Description and SPL, dBA	
					WD: S	Distant Traffic 35-44	
00/02/2021	13:38	EE	41	37		Birds 32-50	
09/02/2021	(Day)	55			WS: 0.5m/s Rain: Nil	Train 35-55	
						Quarry Not Audible	
	Lynwood	Quarry LA	eq(15min) C	ontribution		<30	
	22:57 (Night)		43	37		Insects 35-45	
		58			WD: SW	Distant Traffic 32-46	
11/02/2021					WS: 0.5m/s	Residential Noise 30-32	
					Rain: Nil	Train 35-58	
						Quarry Not Audible	
	Lynwood	<30					
	Lynwood	<40					



#### 4.3 Assessment Results - Location N3

The monitored noise level contributions and observed meteorological conditions for each assessment period at Location N3 for the NMA are presented in **Table 5**.

D-4-	T: (l)	Descript	or (dBA re	20 μPa)	Matazzalazu	December and CDL IDA
Date	Time (hrs)	LAmax	LAeq	LA90	- Meteorology	Description and SPL, dBA
						Distant Traffic 33-40
						Birds 30-48
						Quarry – Haul Trucks <30
						(3 movements, 2-4 minute duration)
	10.51				WD: SW	Quarry – Reverse Alarms <30
09/02/2021	12:51	48	38	35	WS: 0.5m/s	(multiple 3-5 second durations)
	(Day)				Rain: Nil	Quarry – Vehicles enter/exit Site 30-3
						(3 movements, 2-3 minute duration)
						Quarry – Loader <30
						(multiple movements
						6-8 minute duration)
	Lynwood Q	uarry LAeq	(15min) Cor	tribution		32
						Insects 38-50
						Distant Traffic <35-42
						Operator 54
						Quarry – Alarms <30
	22:20	54	43	39	WD: SE	(multiple 3-5 second durations)
11/02/2021					WS: 0.5m/s	Quarry – Train Loading 30-35
	(Night)				Rain: Nil	(6-8 minute duration)
						Quarry - Train Shunting 35-45
						(5 second duration)
						Quarry – Hum <30
						(constant duration)
	Lynwood Q	uarry LAeq		<35		
	Lynwood (	Quarry LA1(		<47		



#### 4.4 Assessment Results - Location N4

The monitored noise level contributions and observed meteorological conditions for each assessment period at Location N4 for the NMA are presented in **Table 6**.

Table 6 Operator-Attended Noise Survey Results – Location N4							
Date	Time (hrs)	Descript	or (dBA re	20 μPa)	Meteorology	Description and SPL, dBA	
Date	Time (fils)	LAmax	LAeq	LA90	weteorology	Description and SPL, dbA	
						Train 35-50	
	14:04				WD: SE	Birds 30-58	
09/02/2021		58	39	35	WS: 1.0m/s	Distant Traffic 30-38	
	(Day)				Rain: Nil	Wind 30-43	
						Quarry Not Audible	
Lynwood Quarry LAeq(15min) Contribution						<30	
	00.00				WD: SW	Insects 32-51	
11/02/2021	23:20	51	42	34	WS: 0.5m/s	Distant Traffic 30-40	
	(Night)				Rain: Nil	Quarry Not Audible	
	Lynwoo		<30				
	Lynwo		<40				



#### 5 Discussion

#### 5.1 Discussion of Results - Location N1

Monitoring on Tuesday 9 February 2021 identified quarry noise was audible during the daytime measurement with quarry noise contributions estimated to satisfy the relevant daytime noise limits. Monitoring on Thursday 11 February 2021 identified quarry noise was inaudible during night-time measurements with quarry noise contributions estimated to satisfy the relevant night-time noise limits. Audible quarry noise sources included the haul truck movements. Extraneous noise sources measured included birds, traffic, train, insects, operator noise, and wind.

#### 5.2 Discussion of Results - Location N2

Monitoring on Tuesday 9 February 2021 and Thursday 11 February 2021 identified quarry noise was inaudible during both daytime and night-time measurements with quarry noise contributions estimated to satisfy the relevant noise limits. Extraneous noise sources measured included birds, traffic, train, insects, and residential noise.

#### 5.3 Discussion of Results - Location N3

Monitoring on Tuesday 9 February 2021 and Thursday 11 February 2021 identified that quarry noise was audible during both daytime and night-time measurements with quarry noise contributions estimated to satisfy the relevant noise limits. Quarry noise sources audible during the survey included the site alarms, vehicle reverse alarms vehicles entering/exiting site, loader movements, haul truck movements, trains loading and shunting and general site hum. Extraneous noise sources included birds, traffic, operator noise and insects.

#### 5.4 Discussion of Results - Location N4

Monitoring on Tuesday 9 February 2021 and Thursday 11 February 2021 identified quarry noise was inaudible during both daytime and night-time measurements with quarry noise contributions estimated to satisfy the relevant noise limits. Extraneous noise sources measured included wind, insects, birds, traffic, and trains.





#### 6 Conclusion

Muller Acoustic Consulting Pty Ltd (MAC) has completed a Noise Monitoring Assessment (NMA) for Holcim (Australia) Pty Ltd at the Lynwood Quarry, Marulan, NSW. The assessment was completed to assess the quarry's compliance with the relevant noise criteria during Quarter 1, ending March 2021.

Attended noise monitoring was undertaken on Tuesday 9 February 2021 and Thursday 11 February 2021 at four representative monitoring locations. The assessment has identified that noise emissions generated by Lynwood Quarry were audible at two locations, however quarry noise emissions were below the relevant noise criteria, satisfying the applicable noise criteria throughout the survey period.





## Appendix A - Glossary of Terms



 Table A1 provides a number of technical terms have been used in this report.


Term	Description
1/3 Octave	Single octave bands divided into three parts
Octave	A division of the frequency range into bands, the upper frequency limit of each band being twice
	the lower frequency limit.
ABL	Assessment Background Level (ABL) is defined in the NPI as a single figure background level for
	each assessment period (day, evening and night). It is the tenth percentile of the measured LA90
	statistical noise levels.
Adverse Weather	Weather effects that enhance noise (that is, wind and temperature inversions) that occur at a site
	for a significant period of time (that is, wind occurring more than 30% of the time in any
	assessment period in any season and/or temperature inversions occurring more than 30% of the
	nights in winter).
Ambient Noise	The noise associated with a given environment. Typically a composite of sounds from many
	sources located both near and far where no particular sound is dominant.
A Weighting	A standard weighting of the audible frequencies designed to reflect the response of the human
	ear to noise.
dBA	Noise is measured in units called decibels (dB). There are several scales for describing noise, the
	most common being the 'A-weighted' scale. This attempts to closely approximate the frequency
	response of the human ear.
dB(Z), dB(L)	Decibels Linear or decibels Z-weighted.
Hertz (Hz)	The measure of frequency of sound wave oscillations per second - 1 oscillation per second
	equals 1 hertz.
LA10	A noise level which is exceeded 10 % of the time. It is approximately equivalent to the average of
	maximum noise levels.
LA90	Commonly referred to as the background noise, this is the level exceeded 90 % of the time.
LAeq	The summation of noise over a selected period of time. It is the energy average noise from a
	source, and is the equivalent continuous sound pressure level over a given period.
LAmax	The maximum root mean squared (rms) sound pressure level received at the microphone during a
	measuring interval.
RBL	The Rating Background Level (RBL) is an overall single figure background level representing
	each assessment period over the whole monitoring period. The RBL is used to determine the
	intrusiveness criteria for noise assessment purposes and is the median of the ABL's.
Sound power level (LW)	This is a measure of the total power radiated by a source. The sound power of a source is a
	fundamental location of the source and is independent of the surrounding environment. Or a
	measure of the energy emitted from a source as sound and is given by :
	= 10.log10 (W/Wo)
	Where: W is the sound power in watts and Wo is the sound reference power at 10-12 watts.



**Table A2** provides a list of common noise sources and their typical sound level.

Table A2 Common Noise Sources and Their Typical Sound Pressure Levels (SPL), dBA						
Source	Typical Sound Level					
Threshold of pain	140					
Jet engine	130					
Hydraulic hammer	120					
Chainsaw	110					
Industrial workshop	100					
Lawn-mower (operator position)	90					
Heavy traffic (footpath)	80					
Elevated speech	70					
Typical conversation	60					
Ambient suburban environment	40					
Ambient rural environment	30					
Bedroom (night with windows closed)	20					
Threshold of hearing	0					

Figure A1 – Human Perception of Sound







ABN: 36 602 225 132 P: +61 2 4920 1833 www.mulleracoustic.com

