

Intended for
Holcim (Australia) Pty Ltd

Document type
Report

Date
February 2024

Project number
318001799

QUARTERLY NOISE MONITORING ASSESSMENT – QUARTER 4 2023 COOMA ROAD QUARRY, GOOGONG, NSW

**QUARTERLY NOISE MONITORING ASSESSMENT –
QUARTER 4 2023
COOMA ROAD QUARRY, GOOGONG, NSW**

Ramboll
The Arc, 45a Watt St
Newcastle, NSW 2300
Australia

T +61 2 4962 5444
<https://ramboll.com>

Project name **Quarterly Noise Monitoring Assessment for Cooma Road Quarry – Quarter 4
2023**
Project no. **318001799**
Recipient **David Manning**
Document type **Report**
Version **1**
Date **01/02/2024**
Prepared by **Jake Bourke, Matilda Englert**
Checked by **Arnold Cho**
Approved by **Belinda Sinclair**
Description **Data collected on 4 and 5 October and 6 November 2023 for the quarterly
period ending December 2023 at Googong, NSW, as part of the noise
monitoring program**

CONTENTS

Abbreviations and Definitions	2
1. Overview	3
1.1 Project Driver	3
1.2 Site Location and Sensitive Receivers	3
2. Noise Criteria	6
3. Methodology	7
4. Results and Discussion	8
4.1 Location N3	8
4.2 Location N8	9
4.3 Location N38	10
4.4 Location N60	11
4.5 Location N67	12
5. Conclusion	13
6. References	14

Tables

Table 1-1: Monitoring locations locality and sensitive receivers	3
Table 2-1: Monitoring locations and noise criteria	6
Table 4-1: Noise survey results and observations for Location N3	8
Table 4-2: Noise survey results and observations for Location N8	9
Table 4-3: Noise survey results and observations for Location N38	10
Table 4-4: Noise survey results and observations for Location N60	11
Table 4-5: Noise survey results and observations for Location N67	12

ABBREVIATIONS AND DEFINITIONS

Ambient Noise	The all-encompassing noise within a given environment. It is the composite of sounds from many sources, both near and far.
Background noise	The underlying level of noise present in the ambient noise, excluding the noise source under investigation, when extraneous noise is removed. This is described using the LA90 descriptor (see below).
dB	Abbreviation for decibel, a measure of sound equivalent to 20 times the logarithm (to base 10) of the ratio of a given sound pressure to a reference pressure, and 10 times the logarithm of a given sound power to a reference power.
dB(A)	A measure of A-weighted sound levels. A Weighting is an adjustment made to the sound level measurement to approximate the response of the human ear.
Extraneous noise	Noise resulting from activities that are not typical of the area. Atypical activities may include construction, and traffic generated by holiday periods. Normal daily traffic is not extraneous noise.
LA1	The noise level, measured in dB(A), which is exceeded for 1 per cent of the measurement period.
LA1(1min)	The noise level, measured in dB(A), which is exceeded for 1 per cent of the time over a 1-minute measurement period, i.e., is exceeded for 0.6 seconds. This measure can approximate to the maximum noise level but may be less if there is more than 1 noise event during this 0.6 second period.
LA10	The noise level, measured in dB(A), which is exceeded for 10 per cent of the time.
LA90	The noise level, measured in dB(A), which is exceeded for 90 per cent of the time, referred to as the background noise level. This is considered to represent the background noise (see above).
LAeq	The level of noise equivalent to the energy average of noise levels occurring over a defined measurement period.
LAeq (period)	The average equivalent noise level, measured in dB(A), during a measurement period (e.g., 15-minute, day, evening, or night).
LAm_{ax}	The A-weighted sound pressure level that represents the maximum noise level measured over the time that a given sound is measured.
NMA	Noise Monitoring Assessment
NMP	Noise Management Plan
SPL	The Sound Pressure Level. Sound pressure is the fluctuation in air pressure, from the steady atmospheric pressure, created by sound. The sound pressure level is the sound pressure expressed on a decibel scale.

Source: Noise Guide for Local Government (NSW EPA, 2023)

1. OVERVIEW

1.1 Project Driver

Ramboll Australia Pty Ltd (Ramboll) has been commissioned by Holcim (Australia) Pty Ltd (Holcim) to complete a Noise Monitoring Assessment (NMA) for Cooma Road Quarry (“the quarry”) at Googong, NSW.

This NMA was done in accordance with the following documents:

- Noise Policy for Industry (NPfI) (NSW EPA, 2017).
- Cooma Road Quarry Noise Management Plan (NMP) (Holcim Australia, 2019).
- Development Consent Application Number SSD_5109 (Minister for Planning and Infrastructure, 2013).
- Environment Protection Licence (EPL) number 1453 (NSW EPA, 2020).
- Australian Standard AS 1055:2018 Acoustics—Description and measurement of environmental noise (Standards Australia, 2018).
- IEC 60942 Ed. 3.0 b:2003 Electroacoustics - Sound calibrators (Standards Australia, 2003).

This NMA has been undertaken for the quarterly period October to December 2023, and forms part of the monitoring program to determine compliance with conditions of the Development Consent.

1.2 Site Location and Sensitive Receivers

The quarry is in Googong, approximately 6 kilometres south of Queanbeyan, NSW.

Sensitive receivers surrounding the quarry are primarily rural and residential properties in all directions. Old Cooma Road is located to the east of the quarry and passing road traffic is a dominate noise source for those receivers to the east of the quarry.

Five monitoring locations have been selected as part of the NMA and in accordance with the Development Consent and are shown in **Table 1-1**.

Table 1-1: Monitoring locations locality and sensitive receivers

Monitoring Locations	Locality and Sensitive Receivers
N3	West of the quarry situated on a rural property off Copperfield Place. This location represents residential and rural receivers to the west of the quarry.
N8	Northeast of the quarry along Tempe Crescent and is representative of residential receivers in that area.
N38	On Heights Road and is representative of the elevated residential receivers to the east of the quarry.
N60	At 501 Old Cooma Road and represents the residence adjacent to the quarry access road.
N67	Situated on a rural property at 732 Old Cooma Road to the south of the quarry. This is representative of rural and residential receivers to the south, with direct line of site into the quarry pit

The monitoring locations with respect to the quarry and assessed receivers are presented in the locality plan shown in **Figure 1**. The NMP states attended monitoring will be undertaken within 30

metres of a private residence, where possible. During this NMA, monitoring at most locations (N3, N8, N60, and N67) was undertaken where safely accessible at each property boundary which was approximately 100 to 200 metres from each property dwelling.

Page left blank for

Figure 1: Noise monitoring locations

2. NOISE CRITERIA

Table 2-1 brings the applicable noise criteria outlined in the Development Consent for the residential receivers surrounding the quarry (N1–N71), and the five monitoring locations adopted from the NMP that are deemed representative and applicable for this NMA (N3, N8, N38, N60, and N67).

Table 2-1: Monitoring locations and noise criteria

Receiver ¹	Monitoring Locations	Morning Shoulder ²	Day ³	Evening ⁴
		LAeq (15min)	LAeq (15min)	LAeq (15min)
		dB(A)		
N1, N7, N8, N56, N57, N59, N63, N64, N65	N8	40	44	39
N67	N67	36	41	35
All other receivers between N9 and N71 inclusive	N60, N38	36	38	35
All other receivers	N3	35	35	35
¹ Refer to Appendix 5 of the Consolidated Development Consent – SSD 5109 (DOC19/541449) and/or the NMP for receiver locations on the map. ² 6 am–7 am Monday to Saturday ³ 7 am–6 pm Monday to Saturday ⁴ 6 pm–10 pm Monday to Saturday Note: No operations on Sundays and public holidays				

3. METHODOLOGY

The monitoring program was developed in accordance with the procedures described in Australian Standard AS 1055:2018 and the Approval Documents referenced in Section 1.

The operator-attended measurements were carried out using a RION Sound Level Meter NL-52 on Wednesday 4 October 2023, Thursday 5 October 2023 and Monday 6 November 2023. The acoustic instrumentation implemented carries current NATA calibration and complies with AS/NZS IEC 61672-1:2013/2002 Class 1. Calibration of all instrumentation was checked prior to and following the measurements using a Pulsar Acoustic Calibrator 105 which also carried a current NATA calibration and complies with IEC 60942:2003. Drift in calibration did not exceed ± 0.3 dBA.

The attended noise monitoring was conducted for 15-minutes in duration during the day, evening, and night periods over three days. Where possible, throughout each measurement the operator(s) quantified the contribution of each significant noise source.

Where the plant was not distinctly audible during the attended monitoring, the quarry contribution is estimated to be at least 10 dBA below the ambient noise level, as determined by the LA90.

4. RESULTS AND DISCUSSION

4.1 Location N3

Noise monitoring at location N3 conducted on Wednesday 4 October 2023, Thursday 5 October 2023 and Monday 6 November 2023 resulted in inaudible quarry noise during morning shoulder and day periods. The quarry was not operational during the evening period. These results satisfy the established noise criteria and indicate that noise emissions from Cooma Road Quarry did not contribute to noise nuisance. The results and observations taken during the monitoring events at Location N3 are presented in **Table 4-1**.

Measured ambient noise sources include background road traffic, birds, wind, rustling trees, aircraft, and a motorbike.

Table 4-1: Noise survey results and observations for Location N3

Date	Time (hrs)	Descriptor (dBA)			Meteorology	Apparent Noise Source, Description and SPL (dBA)	Cooma Road Quarry LAeq(15min) (dBA) Contribution	LAeq(15min) Criteria (dBA)
		L _{Amax}	L _{Aeq}	L _{A90}				
05-10-2023	6:11am to 6:26am (Morning Shoulder)	71.5	52.8	44.6	WD: 340° WS: 3.7 m/s Rain: Nil	Wind/rustling trees 42-71 Birds 48-54 Quarry inaudible	<35	35
04-10-2023	9:15am to 9:30am (Day)	80.4	51.7	41.7	WD: n/a WS: 0 m/s Rain: Nil	Road traffic/birds 39-41 Quarry inaudible	<32	35
06-11-2023	6:00pm to 6:15pm (Evening)	63.4	46.3	37.6	WD: 100° WS: 1.5 m/s Rain: Nil	Background road traffic/birds/ trees rustling 35-410 Aircraft 52-58 (occurred twice for 25 seconds each) Motorbike 40-55 (occurred once for 22 seconds) Quarry not operational	n/a ¹	35

¹ quarry not operational.

4.2 Location N8

Noise monitoring at location N8 on Wednesday 4 October 2023 and Monday 6 November 2023 resulted in inaudible quarry noise during morning shoulder and day periods. The quarry was not operational during the evening period. These results satisfy the established noise criteria and indicate that noise emissions from Cooma Road Quarry did not contribute to noise nuisance. The results and observations taken during the monitoring events at Location N8 are presented in **Table 4-2**.

Measured ambient noise sources included road traffic, passing cars, and birds.

Table 4-2: Noise survey results and observations for Location N8

Date	Time (hrs)	Descriptor (dBA)			Meteorology	Apparent Noise Source, Description and SPL (dBA)	Cooma Road Quarry LAeq(15min) (dBA) Contribution	LAeq(15min) Criteria (dBA)
		LAmx	LAeq	LA90				
04-10-2023	6:43am to 6:58am (Morning Shoulder)	65.9	50.8	46.1	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 41-63 Birds 46-51 Cars on Tempe Cres. 60-66 Quarry inaudible	<36	40
04-10-2023	8:17am to 8:32am (Day)	93.8	56.6	46.7	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 42-67 Birds 46-48 Cars on Tempe Cres. 53-93 Quarry inaudible	<37	44
06-11-2023	6:29pm to 6:44pm (Evening)	77.9	59.5	49.9	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 38-77 Quarry not operational	n/a ¹	39

¹ quarry not operational.

4.3 Location N38

Noise monitoring at location N38 conducted on Wednesday 4 October 2023, Thursday 5 October 2023 and Monday 6 November 2023 resulted in inaudible quarry noise during morning shoulder and day periods. The quarry was not operational during the evening period. These results satisfy the established noise criteria and indicate that noise emissions from Cooma Road Quarry did not contribute to noise nuisance. The results and observations taken during the monitoring events at Location N38 are presented in **Table 4-3**.

Measured ambient noise sources included road traffic, passing cars on Tempe Crescent, and birds.

Table 4-3: Noise survey results and observations for Location N38

Date	Time	Descriptor (dBA)			Meteorology	Apparent Noise Source, Description and SPL (dBA)	Cooma Road Quarry LAeq(15min) (dBA) Contribution	LAeq(15min) Criteria (dBA)
		LAmx	LAeq	LA90				
05-10-2023	6:36am to 6:51am (Morning Shoulder)	72.5	53	34.4	WD: 330° WS: 3 m/s Rain: Nil	Background road traffic 29-50 Birds 50-73 Quarry inaudible	<24	36
04-10-2023	8:34am to 8:49am (Day)	82.1	46.8	33.3	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 32-80 Cars on Tempe Cres. 31-82 Quarry inaudible	<23	38
06-11-2023	6:48pm to 7:03pm (Evening)	71.8	53.7	43.4	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 35-71 Birds 51-53 Quarry not operational	n/a ¹	35

¹ quarry not operational.

4.4 Location N60

Noise monitoring at location N60 conducted on Wednesday 4 October 2023 and Monday 6 November 2023 resulted in inaudible quarry noise during morning shoulder and day periods. The quarry was not operational during the evening period. These results satisfy the established noise criteria and indicate that noise emissions from Cooma Road Quarry did not contribute to noise nuisance. The results and observations taken during the monitoring events at Location N60 are presented in **Table 4-4**.

Measured ambient noise sources included road traffic, birds, and insects.

Table 4-4: Noise survey results and observations for Location N60

Date	Time	Descriptor (dBA)			Meteorology	Apparent Noise Source, Description and SPL (dBA)	Cooma Road Quarry LAeq(15min) (dBA) Contribution	LAeq(15min) Criteria (dBA)
		L _{Amax}	L _{Aeq}	L _{A90}				
04-10-2023	6:20am to 6:35am (Morning Shoulder)	74.4	61.8	48.1	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 43-74 (~ every 8 sec for 10 sec) Birds 40-50 Quarry inaudible	<33 ²	36
04-10-2023	7:34am to 7:49am (Day)	73.9	63.1	54.1	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 44-73 Quarry inaudible	<32	38
06-11-2023	7:26pm to 7:41pm (Evening)	71.3	57.7	44	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 33-71 Insects 39-43 Quarry not operational	n/a ¹	35

¹ quarry not operational.

² estimated based on observed background road traffic using LAeq.

4.5 Location N67

Noise monitoring at location N67 conducted on Wednesday 4 October 2023 and Monday 6 November 2023 resulted in inaudible quarry noise during morning shoulder and day periods. The quarry was not operational during the evening period. These results satisfy the established noise criteria and indicate that noise emissions from Cooma Road Quarry did not contribute to noise nuisance. The results and observations taken during the monitoring events at Location N67 are presented in **Table 4-5**.

Measured ambient noise sources included road traffic, birds, and insects.

Table 4-5: Noise survey results and observations for Location N67

Date	Time	Descriptor (dBA)			Meteorology	Apparent Noise Source, Description and SPL (dBA)	Cooma Road Quarry LAeq(15min) (dBA) Contribution	LAeq(15min) Criteria (dBA)
		L _{Amax}	L _{Aeq}	L _{A90}				
04-10-2023	6:00am to 6:15am (Morning Shoulder)	96	66.8	46.6	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 43-74 (~ every 6 sec for 12 sec) Birds 46-51 Quarry inaudible	<33 ²	36
04-10-2023	8:08am to 8:23am (Day)	100.8	68.7	50.6	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 42-100 Quarry inaudible	<41	41
06-11-2023	7:07pm to 7:22pm (Evening)	78.8	62	44.4	WD: n/a WS: 0 m/s Rain: Nil	Background road traffic 35-78 Insects 40-51 Quarry not operational	n/a ¹	35

¹ quarry not operational.

² estimated based on observed background road traffic using LAeq.

5. CONCLUSION

This NMA was completed by Ramboll at the Holcim Cooma Road Quarry, Googong, NSW as a quarterly requirement of the NMP. Monitoring was carried out on Wednesday 4 October 2023, Thursday 5 October 2023 and Monday 6 November 2023 at five locations selected as representative to the sensitive receivers at the surroundings to Cooma Road Quarry. No exceedances of the noise criteria were recorded, and quarry noise was inaudible at the selected monitoring locations during the monitoring campaign. The quarry was not operational during the evening periods.

The results presented in this NMA show compliance with the relevant noise criteria applicable to the operation of the Holcim Cooma Road Quarry, Googong, NSW.

6. REFERENCES

Holcim Australia (2019) *Cooma Road Quarry, Noise Management Plan*.

Minister for Planning and Infrastructure (2013) 'Development Consent SSD_5109, Cooma Road Quarry Continued Operations Project'.

NSW EPA (2020) Environment Protection Licence number 1453

NSW EPA (2013) *Noise Guide for Local Government*. Sydney NSW: NSW Environment Protection Authority. Available at: <https://www.epa.nsw.gov.au/-/media/epa/corporate-site/resources/noise/20130127nlg.pdf> (Accessed: 25 October 2022).

NSW EPA (2017) *Noise Policy for Industry (NPfI)*. Sydney NSW: NSW Environment Protection Authority. Available at: <https://www.epa.nsw.gov.au/-/media/epa/corporate-site/resources/noise/17p0524-noise-policy-for-industry.pdf> (Accessed: 25 October 2022).

Standards Australia (2018) *AS 1055:2018 Acoustics—Description and measurement of environmental noise*. Australian Standard. Available at: https://infostore.saiglobal.com/preview/825367946534.pdf?sku=1131503_SAIG_AS_AS_2626154 (Accessed: 19 January 2023).

Standards Australia (2003) *AS 60942:2003 Electroacoustics - Sound calibrators*. Australian Standard.