

Blast monitoring summary

Beenleigh Quarry | April 2025 - June 2025

Blast Date	Blast No.	Vibration Type	Leaver Crt	Top of Vennor Dr	92 Peachey Rd	Quarry Office
17-Apr-25	955	Ground Vibration (mm/s)	0.98	Did Not Register	0.71	1.57
17-Apr-25	955	Airover Pressure (dBL)	99.20	Did Not Register	88.00	94.60
27-May-25	956	Ground Vibration (mm/s)	1.20	0.32	0.73	2.53
27-May-25	956	Airover Pressure (dBL)	103.50	99.90	103.30	95.20
17-Jun-25	957	Ground Vibration (mm/s)	0.43	0.11	0.36	0.66
17-Jun-25	957	Airover Pressure (dBL)	109.20	110.20	110.90	112.30

Results

All blast monitoring results from April 2025 - June 2025 are compliant with the site's Environmental Authority blasting limits. Monitoring locations are selected by the consultant based on blast profile and location on site. The result "Did Not Register" indicates no impact occurred at a level sufficient for the monitor to record.

Further information

Contact **Beau Patton**, Beenleigh Quarry Manager, on 0448 243 591 to provide feedback or request further information.