

Blast monitoring summary

Beenleigh Quarry | February 2025 - March 2025

Blast Date	Blast No.	Vibration Type	Leaver Crt	Top of Vennor Dr	92 Peachey Rd	Quarry Office
11-Feb-25	952	Ground Vibration (mm/s)	0.32	Did Not Register	Did Not Register	0.44
11-Feb-25	952	Air over Pressure (dBL)	88.00	Did Not Register	Did Not Register	100.00
04-Mar-25	953	Ground Vibration (mm/s)	Did Not Register	Did Not Register	Did Not Register	Did Not Register
04-Mar-25	953	Air over Pressure (dBL)	Did Not Register	Did Not Register	Did Not Register	Did Not Register

Results

All blast monitoring results from February 2025 - March 2025 are compliant with the site's Environmental Authority blasting limits. Monitoring locations are selected by the consultant based on blast profile and location on site. The result "Did Not Register" indicates no impact occurred at a level sufficient for the monitor to record.

Further information

Contact **Beau Patton**, Beenleigh Quarry Manager, on 0448 243 591 to provide feedback or request further information.