

# Blast monitoring summary

Beenleigh Quarry | March 2026 - June 2026

Blast Date	Blast No.	Vibration Type	Leaver Crt	Top of Vennor Dr	92 Peachey Rd
23-Mar-26	2603	Ground Vibration (mm/s)	0.38	Did Not Register	0.96
23-Mar-26	2603	Airover Pressure (dBL)	107.80	Did Not Register	105.00
08-Apr-26	2604	Ground Vibration (mm/s)	Did Not Register	Did Not Register	0.45
08-Apr-26	2604	Airover Pressure (dBL)	Did Not Register	Did Not Register	104.00
22-Apr-26	2605	Ground Vibration (mm/s)	0.90	0.06	0.61
22-Apr-26	2605	Airover Pressure (dBL)	101.70	110.30	101.80
13-May-26	2606	Ground Vibration (mm/s)	1.13	0.57	1.02
13-May-26	2606	Airover Pressure (dBL)	108.30	110.90	107.60
02-Jun-26	2607	Ground Vibration (mm/s)	1.90	0.47	1.47
02-Jun-26	2607	Airover Pressure (dBL)	93.90	108.40	101.80
15-Jun-26	2608	Ground Vibration (mm/s)	1.13	0.26	1.24
15-Jun-26	2608	Airover Pressure (dBL)	102.40	109.00	100.80

## Results

All blast monitoring results from March 2026 to June 2026 are compliant with the site's Environmental Authority blasting limits. Monitoring locations are selected by the consultant based on blast profile and location on site. The result "Did Not Register" indicates no impact occurred at a level sufficient for the monitor to record.

## Further information

Contact **Beau Patton**, Beenleigh Quarry Manager, on 0448 243 591 to provide feedback or request further information.