Intended for

Holcim (Australia) Pty Ltd

Document type

Report

Date

May 2024

Lynwood Quarry Quarterly Noise Monitoring Assessment

Quarter 1 2024



Lynwood Quarry Quarterly Noise Monitoring Assessment

Quarter 1 2024

Project name NSW Environmental Monitoring 2023-2024

Project no. **318001799**Recipient **Wayne Beattie**

1

Document type **Report**

Version

Date **06/05/2024**

Prepared by Jake Bourke, Matilda Englert

Checked by Arnold Cho
Approved by Belinda Sinclair

Description Data collected on 22 and 23 of January and 6 March 2024 for the quarterly

period ending March 2024 at Marulan, NSW, as part of the noise monitoring

program

Ramboll

The Arc, 45a Watt St Newcastle, NSW 2300

Australia

T +61 2 4962 5444 https://www.ramboll.com/

Contents

Abbre	eviations and Definitions	2
1.	Overview	3
1.1	Project Driver	3
1.2	Site Location and Sensitive Receptors	3
2.	Noise Criteria	5
3.	Methodology	6
3.1	Meteorological Conditions	6
4.	Results and Discussion	7
4.1	Location N1	7
4.2	Location N2	8
4.3	Location N3	9
4.4	Location N4	10
5.	Conclusion	11
6.	References	12
	Tables	
	Table 2-1: Monitoring locations and noise criteria	5
	Table 3-1: Classification of Atmospheric Stability (NSW EPA, 2014)	6
	Table 4-1: Noise survey results and observations for Location N1	7
	Table 4-2 Noise survey results and observations for Location N2	8
	Table 4-3: Noise survey results and observations for Location N3	9
	Table 4-4: Noise survey results and observations for Location N4	10

Appendices

Appendix 1

Sound Exposure Level Calculation

Abbreviations and Definitions

Ambient	The all-encompassing noise within a given environment. It is the composite of
Noise	sounds from many sources, both near and far.
Background noise	The underlying level of noise present in the ambient noise, excluding the noise source under investigation, when extraneous noise is removed. This is described
	using the LA90 descriptor (see below).
dB	Abbreviation for decibel, a measure of sound equivalent to 20 times the logarithm (to base 10) of the ratio of a given sound pressure to a reference pressure, and 10 times the logarithm of a given sound power to a reference power.
dB(A)	A measure of A-weighted sound levels. A Weighting is an adjustment made to the sound level measurement to approximate the response of the human ear.
Extraneous	Noise resulting from activities that are not typical of the area. Atypical activities
noise	may include construction, and traffic generated by holiday periods. Normal daily traffic is not extraneous noise.
LA1	The noise level, measured in dB(A), which is exceeded for 1 per cent of the measurement period.
LA1(1min)	The noise level, measured in dB(A), which is exceeded for 1 per cent of the time over a 1-minute measurement period, i.e., is exceeded for 0.6 seconds. This measure can approximate to the maximum noise level but may be less if there is more than 1 noise event during this 0.6 second period.
LA10	The noise level, measured in dB(A), which is exceeded for 10 per cent of the time.
LA90	The noise level, measured in dB(A), which is exceeded for 90 per cent of the time, referred to as the background noise level. This is considered to represent the background noise (see above).
LAeq	The level of noise equivalent to the energy average of noise levels occurring over a defined measurement period.
LAeq	The average equivalent noise level, measured in dB(A), during a measurement
(period)	period (e.g., 15-minute, day, evening, or night).
LAmax	The A-weighted sound pressure level that represents the maximum noise level measured over the time that a given sound is measured.
NMA	Noise Monitoring Assessment
NMP	Noise Management Plan
SPL	The Sound Pressure Level. Sound pressure is the fluctuation in air pressure, from the steady atmospheric pressure, created by sound. The sound pressure level is the sound pressure expressed on a decibel scale.

Source: Noise Guide for Local Government (NSW EPA, 2023)

1. Overview

1.1 Project Driver

Ramboll Australia Pty Ltd (Ramboll) has been commissioned by Holcim (Australia) Pty Ltd (Holcim) to complete a Noise Monitoring Assessment (NMA) for Lynwood Quarry ("the quarry") at Marulan, NSW.

This NMA was done in accordance with the following documents:

- Noise Policy for Industry (NPfI) (NSW EPA, 2017).
- Lynwood Quarry Noise Management Plan (NMP) (Holcim Australia, 2019).
- Environment Protection Licence (EPL) number 12939 (NSW EPA, 2021).
- Development Consent DA 128-5-2005 (Minister for Planning, 2017).
- Australian Standard AS 1055:2018 Acoustics Description and measurement of environmental noise (Standards Australia, 2018).
- IEC 60942 Ed. 3.0 b:2003 Electroacoustics Sound calibrators (Standards Australia, 2003).

This NMA has been undertaken for the quarterly period January to March 2024, and forms part of the monitoring program to determine compliance with conditions of the Development Consent.

1.2 Site Location and Sensitive Receptors

The quarry is located at 278 Stoney Creek Road, approximately 4 km to the west of the Marulan railway station and town centre. Sensitive receptors surrounding the quarry are primarily rural and residential (to the west of the site). The Hume Highway is located to the east and south of the quarry. Highway traffic (Hume Highway) is a dominant noise source.

The monitoring locations with respect to the quarry and assessed receivers are presented in the locality plan in **Figure 1**.



Legend

- Noise monitoring location
- Residence/noise assessment location

Figure 1: Noise monitoring locations at Lynwood Quarry



2. Noise Criteria

Table 2-1 includes the applicable noise criteria outlined in the Development Consent and the EPL for the 16 residential receivers surrounding the quarry (L1–L16), and the four monitoring locations adopted from the NMP that are deemed representative and applicable for this NMA (N1–N4). It should be noted that the original location of N3 (on the northern boundary of 16038 Hume Highway, Marulan) continues to be inaccessible and as such N3 has been relocated to a nearby residential receiver approximately 900 m to the west on Munro Road, Marulan (**Figure 1**) where all future monitoring will take place. This revised location is deemed representative and applicable for this NMA.

Table 2-1: Monitoring locations and noise criteria

		Moni	toring Locations	Day ¹	Evening ²	Night ³	Night ³
EPL ID			Address	LAeq (15min)	LAeq (15min)	LAeq (15min)	LA1 (1min)
		ID			dE	SA.	
L1	West of the Granite Pit.	N1	1114 Carrick Road, Marulan	35	35	35	45
L2	Northeast of the site	-	-	35	35	35	45
L3	Northeast of the site	-	-	35	35	35	45
L4	East of the site in Marulan	-	-	35	37	35	46
L5	East of the site in Marulan	-	-	35	35	35	46
L6	East of the site in Marulan	N2	End of Maclura Drive, Marulan	35	37	36	46
L7	East of the site in Marulan	-	-	38	38	35	55
L8	East of the site in Marulan	-	-	39	38	36	55
L9	East of the site in Marulan	-	-	39	39	37	56
L10	Southeast of the site in Old Marulan	-	-	42	42	40	53
L11	South of the site	N3	Off Marulan South Road, near DD8	35	35	36	47
L12	East of the site in Marulan	N4	Corner of Dorsett and Suffolk Road, Marulan	37	37	36	47
L13	East of the site in Marulan	-	-	40	38	37	47
L14	South of the site	ı	-	35	35	35	47
L15	South of the site	ī	-	35	35	35	47
L16	Northeast of the site	-	-	35	35	35	45

¹7 am-6 pm Monday to Saturday and 8 am-6 pm Sunday and public holidays

 $^{^{2}}$ 6 pm–10 pm Monday to Sunday

³ 10 pm-7 am Monday to Saturday and 10 pm-8 am Sunday and public holidays

3. Methodology

The monitoring program was designed in accordance with the procedures described in Australian Standard AS 1055:2018 and the Approval Documents referenced in Section 1. The measurements were carried out using a RION Sound Level Meter NL-52 on Monday 22 January, Tuesday 23 January and Wednesday 6 March 2024. The acoustic instrumentation used carries current NATA calibration and complies with AS/NZS IEC 61672-1:2013/2002 class 1. Calibration of all instrumentation was checked prior to and following measurements using a Pulsar Acoustic Calibrator 105 which carried a current NATA calibration and complies with IEC 60942:2003. Drift in calibration did not exceed ±0.3 dBA.

Attended noise monitoring was conducted for 15-minutes in duration during the day, evening, and night periods over three days. Where possible, throughout each measurement the operator quantified the contribution of each significant noise source.

Where the quarry was not distinctly audible during the attended monitoring, the quarry contribution is estimated to be at least 10 dBA below the ambient noise level, as determined by the LA90.

3.1 Meteorological Conditions

Extremely stable

Meterology has an important influence on noise monitoring assessment. Where an onsite meterological station with data recorded at 10m height has not been available, the nearest Bureau of Meteorology data has been adopted to inform this assessment and modelled using The Air Pollution Model (TAPM) to determine the atmospheric stability category as outline in **Table 3-1.**

Stability Classification	Pasquill Stability Category	Ambient temperature change with height (°C/100m)
Extremely unstable	A	ΔT ≤ -1.9
Moderately unstable	В	-1.9 < ΔT ≤ -1.7
Slightly unstable	С	-1.7 < ΔT ≤ -1.5
Neutral	D	-1.5 < ΔT ≤ -0.5
Slightly stable	Е	-0.5 < ΔT ≤ 1.5
Moderately stable	F	1.5 < ΔT ≤ 4.0

G

Table 3-1: Classification of Atmospheric Stability (NSW EPA, 2014)

As stated in the Development Consent, the noise criteria in **Table 2-1** applies under all meteorological conditions except the following:

- Monitoring locations for the collection of representative noise data
- Wind speeds greater than 3 m/s at 10 metres above ground level
- Stability category F temperature inversion conditions and wind speeds greater than 2 m/s at 10 metres above ground level
- Stability category G temperature inversion conditions.

Appendix 10 of the Development Consent also specifies that except for wind speed at microphone height, the data to be used for determing meterological conditions must be that recorded by a suitable meteorological station operating in the vicinity of the site that complies with the requirements in the Approved Methods for Sampling of Air Pollutants in New South Wales quideline.

 $\Delta T > 4.0$

4. Results and Discussion

4.1 Location N1

Noise monitoring at location N1 was conducted on Monday 22 January, Tuesday 23 January and Wednesday 6 March 2024. Noise from the quarry was inaudible during the day, evening, and night monitoring periods, with the ambient noise environment dominated by birds, insects, trees/wind, motorway hum, dogs, and horses in surrounding paddocks. The results meet the established noise criteria and indicate that noise emissions from Lynwood Quarry did not contribute to noise nuisance at the time of the monitoring. The results and observations taken during the monitoring events at Location N1 are presented in **Table 4-1**.

Table 4-1: Noise survey results and observations for Location N1

		Des	criptor (d	iBA)							
Date	Time	LA1	LAeq	LA90	Meteorology (Handheld at microphone height)	Onsite Met Station (10m height)	Apparent Noise Source, Description and SPL (dBA)	Lynwood Quarry LAeq(15min) Contribution (dBA)	LAeq(15min) Criteria (dBA)	Lynwood Quarry LA1(1min) Contribution (dBA)	LA1(1min) Criteria (dBA)
23-01-24	7:00am to 7:15am (Day)	51.5	40.0	29.0	WD: n/a WS: 0 m/s Rain: Nil	WD: 146° WS: 1.3 m/s Rain: nil Stability Category: D ¹	Insects 25-31 Birds 33-56 Quarry inaudible	<19	35	n/a	n/a
22-01-24	6:03pm to 6:18pm (Evening)	52.2	43.6	38.6	WD: 271° WS: 0.5 m/s Rain: Nil	WD: 117° WS: 3.8 m/s Rain: nil Stability Category: D¹	Wind/trees 35-48 Birds 39-53 Dogs 40-61 Quarry inaudible	<29	35	n/a	n/a
06-03-24	6:23am to 6:42am (Night)	41.9	32.4	28.3	WD: n/a WS: 0 m/s Rain: Nil	WD: 319° WS: 7.2 m/s Rain: nil Stability Category: E¹	Motorway hum 26 Birds 40-47 Horses galloping 44- 45 Quarry inaudible	<18	35	<42	45

¹ Temperature data modelled using TAPM to determine Stability Category.

4.2 Location N2

Noise monitoring at location N2 was conducted on Monday 22 January and Tuesday 23 January 2024. Noise from the quarry was inaudible during the day, evening, and night monitoring periods, with the ambient noise environment dominated by motorway traffic, birds, and a passing train. The results meet the established noise criteria and indicate that noise emissions from Lynwood Quarry did not contribute to noise nuisance at the time of the monitoring. The results and observations taken during the monitoring events at Location N2 are presented in **Table 4-2**.

Table 4-2 Noise survey results and observations for Location N2

		Des	criptor (d	BA)				_		_	
Date	Time	LA1	LAeq	LA90	Meteorology (handheld at microphone height)	Onsite Met Station (10m height)	Apparent Noise Source, Description and SPL (dBA)	Lynwood Quarry LAeq (15min) Contribution (dBA)	LAeq (15min) Criteria (dBA)	Lynwood Quarry LA1(1min) Contribution (dBA)	LA1 (1min) Criteria (dBA)
23-01-24	8:43am to 8:58am (Day)	47.1	40.2	37.3	WD: n/a WS: 0 m/s Rain: Nil	WD: 143° WS: 1.2 m/s Rain: nil Stability Category: D¹	Background motorway 34-40 Birds 40-53 Quarry inaudible	<27	35	n/a	n/a
22-01-24	7:06pm to 7:21pm (Evening)	49.0	43.6	40.5	WD: 233 WS: 0.6 m/s Rain: Nil	WD: 93° WS: 1.8 m/s Rain: nil Stability Category: D¹	Background motorway 37-44 Birds 40-54 Train 49-53 Quarry inaudible	<31	37	n/a	n/a
23-01-24	6:00am to 6:15am (Night)	44.8	39.8	36.9	WD: n/a WS: 0 m/s Rain: Nil	WD: 150° WS: 0.5 m/s Rain: nil Stability Category: E ¹	Background motorway 33-41 Birds 39-55 Quarry inaudible	<27	36	<45	46

 $^{^{1}}$ Temperature data modelled using TAPM to determine Stability Category.

4.3 Location N3

Noise monitoring at location N3 was conducted on Monday 22 January, Tuesday 23 January and Wednesday 6 March 2024. Noise from the quarry was inaudible during the day and evening monitoring periods. Audible quarry noise was identified during the night period. Site vehicles on the quarry entrance road were observed and measured during the night monitoring period for up to twelve seconds on three occasions, however, noise emission is below the 15min LAeq criteria using sound level exposure calculations also included in **Appendix 1**. The ambient noise environment was dominated by motorway traffic and birds. The results meet the established noise criteria and indicate that noise emissions from Lynwood Quarry did not contribute to noise nuisance at the time of the monitoring. The results and observations taken during the monitoring events at Location N3 are presented in **Table 4-3**.

Table 4-3: Noise survey results and observations for Location N3

		Des	criptor (d	BA)							
Date	Time	1A1	LAeq	1.490	Meteorology (handheld at microphone height)	Onsite Met Station (10m height)	Apparent Noise Source, Description and SPL (dBA)	Lynwood Quarry LAeq (15min) Contribution (dBA)	LAeq (15min) Criteria (dBA)	Lynwood Quarry LA1(1min) Contributio n (dBA)	LA1 (1min) Criteria (dBA)
23-01-24	9:16am to 9:31am (Day)	41.4	36.7	34.2	WD: n/a WS: 0 m/s Rain: Nil	WD: 165° WS: 1.3 m/s Rain: nil Stability Category: D¹	Motorway hum 32-35 Birds 33-59 Quarry inaudible	<24	35	n/a	n/a
22-01-24	7:35pm to 7:50pm (Evening)	48.0	39.9	35.8	WD: n/a WS: 0 m/s Rain: Nil	WD: 108° WS: 2.1 m/s Rain: nil Stability Category: E ¹	Motorway hum 33-39 Birds 36-61 Quarry inaudible	<26	35	n/a	n/a
06-03-24	5:37am to 5:52am (Night)	48.4	40.4	36.7	WD: n/a WS: 0 m/s Rain: Nil	WD: 343° WS: 4.6 m/s Rain: nil Stability Category: E ¹	Motorway hum 33-38 Birds 40-54 Holcim vehicles on quarry entrance road 37-43 (occurred 3 times for 10-12 seconds each) Quarry audible	<29 ²	<36	<48³	47

¹ Temperature data modelled using TAPM to determine Stability Category.

² value estimated based on sound exposure level calculation in **Appendix 1**.

³ Measured LA1 was dominated by background motorway traffic and birds.

4.4 Location N4

Noise monitoring at location N4 was conducted on Monday 22 January and Tuesday 23 January 2024. Noise from the quarry was inaudible during the day, evening, and night monitoring periods, with the ambient noise environment dominated by motorway traffic, wind, trees, and birds. The results meet the established noise criteria and indicate that noise emissions from Lynwood Quarry did not contribute to noise nuisance at the time of the monitoring. The results and observations taken during the monitoring events at location N4 are presented in **Table 4-4**.

Table 4-4: Noise survey results and observations for Location N4

		Des	criptor (d	BA)							
Date	Time	LA1	LAeq	LA90	Meteorology (Handheld at microphone height)	Onsite Met Station (10m height)	Apparent Noise Source, Description and SPL (dBA)	Lynwood Quarry LAeq (15min) Contribution (dBA)	LAeq (15min) Criteria (dBA)	Lynwood Quarry LA1(1min) Contribution (dBA)	LA1 (1min) Criteria (dBA)
23-01-24	8:27am to 8:42am (Day)	45.3	38.2	33.9	WD: n/a WS: 0 m/s Rain: Nil	WD: 143° WS: 1.2 m/s Rain: nil Stability Category: E ¹	Motorway 31-36 Birds 40-57 Quarry inaudible	<24	37	n/a	n/a
22-01-24	6:40pm to 6:55pm (Evening)	46.3	40.9	37.8	WD: 233 WS: 0.7 m/s Rain: Nil	WD: 107° WS: 2.1 m/s Rain: nil Stability Category: D¹	Wind/trees/motorway 34-40 Birds 41-44 Quarry inaudible	<28	37	n/a	n/a
23-01-24	6:35am to 6:50am (Night)	43.6	37.8	34.8	WD: n/a WS: 0 m/s Rain: Nil	WD: 163° WS: 0.9 m/s Rain: nil Stability Category: E¹	Motorway 32-38 Birds 40-55 Quarry inaudible	<25	36	<47	47

¹ Temperature data modelled using TAPM to determine Stability Category.

5. Conclusion

This NMA was completed by Ramboll at the Holcim Lynwood Quarry, Marulan, NSW as a quarterly requirement of the NMP. Monitoring was carried out on Monday 22 January, Tuesday 23 January and Wednesday 6 March 2024 at four locations selected as representative to the sensitive receptors at the surroundings to Lynwood Quarry. No audible noise from quarry operations was recorded at any of the four locations during the day, evening, and night periods. The LA1 quarry contribution also exceeded the LA1(1min) (dBA) criteria for N3 but it was noted that LA1 was dominated by birds and road traffic at this location.

The results presented in this NMA show compliance with the relevant noise criteria at the Holcim Lynwood Quarry, Marulan, NSW, except for the night LA1 contribution at N3.

6. References

Holcim Australia (2019) Lynwood Quarry, Noise Management Plan.

Minister for Planning and Infrastructure (2005) 'Development Consent DA 128-5-2005, Lynwood Hard Rock Quarry, and associated infrastructure'.

NSW EPA (2021) Environment Protection Licence number 12939

NSW EPA (2013) *Noise Guide for Local Government*. Sydney NSW: NSW Environment Protection Authority. Available at: https://www.epa.nsw.gov.au/-/media/epa/corporate-site/resources/noise/20130127nglg.pdf (Accessed: 25 October 2022).

NSW EPA (2014) Discussion Paper. Validation of Inversion Strength Estimation Method.

NSW EPA (2017) *Noise Policy for Industry (NPfI)*. Sydney NSW: NSW Environment Protection Authority. Available at: https://www.epa.nsw.gov.au/-/media/epa/corporate-site/resources/noise/17p0524-noise-policy-for-industry.pdf (Accessed: 25 October 2022).

Standards Australia (2018) AS 1055:2018 Acoustics—Description and measurement of environmental noise. Australian Standard. Available at: https://infostore.saiglobal.com/preview/825367946534.pdf?sku=1131503_SAIG_AS_AS_262615 4 (Accessed: 19 January 2023).

Standards Australia (2003) *AS 60942:2003 Electroacoustics - Sound calibrators.* Australian Standard.

Appendix 1
Sound Exposure Level Calculation

Sound Exposure Level Calculation

Project No: 318001799 Client Name: Holcim Australia Pty Ltd

Project Name: NSW Environmental Monitoring

Project Site: Lynwood Quarry

6/05/2024



N3 night monitoring period (5:37AM - 5:52AM)

Noise source	Holcim machinery
Meas. Dist from source (m)	=
Meas. Time (s)	12
Meas. LAeq dB	43
Calc Sel dB	54
No. Events in 15min	3
Total LAeq (15min)	29